



## WASHTENAW COUNTY ROAD COMMISSION

### TOWNSHIP/STAFF REPORT – July 2, 2019

For the period of June 10 thru June 23, 2019

## TOWNSHIP REPORT

---

### OPERATIONS REPORT

#### MAINTENANCE

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

#### ANN ARBOR TOWNSHIP

- Crack Sealing – Earhart Road
- Fallen Trees – Westridge Road

#### AUGUSTA TOWNSHIP

- Boom Mow – Whittaker Road, Willis Road, Willow Road
- Limestone Patch – Pitman Road, Tuttle Hill Road: 45 tons
- Set Barricades – Judd Road

#### BRIDGEWATER TOWNSHIP

- Culvert Replacement – Hogan Road
- Limestone Patch – Burmeister Road, Hack Road, Hogan Road, Kies Road, Lima Center Road, Wilbur Road, Willow Road: 155 tons
- Local Road Dust Control

#### DEXTER TOWNSHIP

- Boom Mow – N Territorial Road
- Fallen Trees – Brand Road, Dexter-Pinckney Road, Hankerd Road
- Gravel Patch – Webbs Shore Drive: 12 tons
- Limestone Patch – Orchard Street, Stofer Court, Winston Road: 42 tons
- Gravel Patch Shoulders – Dexter-Pinckney Road, N Territorial Road: 20 tons
- Local Road Dust Control

#### FREEDOM TOWNSHIP

- Drainage and Backslopes – Lindemann Road
- Fallen Trees – Waters Road
- Gravel Patch – Hieber Road: 12 tons
- Limestone patch – Esch Road, Ellsworth Road, Hieber Road, Saline Waterworks Road, Steinbach Road, Waters Road: 140 tons
- Parker Road Limestone Resurfacing Project – 553 tons

## LIMA TOWNSHIP

- Preparing Bridge Approaches and Final Grading - Dexter-Chelsea Border-To-Border Trail
- Drainage and Backslopes – N Dancer Road
- Fallen Trees – Gross Road, McKinley Road, Trinkle Road
- Gravel Patch – Fletcher Road, Sager Road, Waltrous Road: 8 tons
- HMA Base – Dexter-Chelsea Border-To-Border Trail
- Limestone Patch – Fletcher Road, Guenther Road, Trinkle Road: 102 tons
- Local Road Dust Control

## LODI TOWNSHIP

- Crack Sealing – Textile Road
- Gravel Patch – Tessmer Road: 17 tons
- Limestone Patch – Abel Road, Alber Road, Bethel Church Road, Clover Drive, Dell Road, Ellsworth Road, Grass Road, Harvest Road, Lindemann Road, Noble Road, S Parker Road, Surrey Drive, W Textile Road, Weber Road, Zeeb Road: 162 tons
- Local Road Dust Control
- Lindemann Road Limestone Resurfacing Project – 3,231 tons

## LYNDON TOWNSHIP

- Boom Mow – Beeman Road, Boyce Road, Bowdish Road, Joslin Lake Road, Osius Road, Roe Road, Roepke Road
- Fallen Trees – Joslin Lake Road, Waterloo Road
- Limestone Patch – Beeman Road, Island Lake Road, Jaycox Road: 15 tons
- Local Road Dust Control

## MANCHESTER TOWNSHIP

- Fallen Trees – Sharon Hollow Road
- Gravel Patch – Below Road, Herman Road: 30 tons
- Limestone Patch – Grossman Road, Herman Road, Kuhl Road, Noggles Road, Tracey Road, Wellwood Road: 84 tons
- Local Road Dust Control
- Primary Road Dust Control

## NORTHFIELD TOWNSHIP

- Fallen Trees – Earhart Road, Jennings Road, Six Mile Road
- Limestone Patch – Eight Mile Road, Hellner Road, Kearney Road, Six Mile Road, Spencer Road: 166 tons

## PITTSFIELD TOWNSHIP

- Drainage and Backslopes – Ellsworth Road, Lohr Road, State Road
- Limestone Patch Shoulders – Bemis Road, Carpenter Road, Crane Road, Ellsworth Road, Fosdick Road, Lohr Road, Moon Road, Maple Road, Textile Road: 28 tons
- Local Road Dust Control
- Replace Manhole Lid – Textile Road
- Roadside Debris – Ellsworth Road, Platt Road, State Road

## SALEM TOWNSHIP

- Crack Sealing – Textile Road
- Boom Mow – Pontiac Trail, Seven Mile Road, Tower Road
- Fallen Trees – Pontiac Trail, Tower Road
- Limestone Patch – Five Mile Road: 19 tons
- Local Road Dust Control

## SALINE TOWNSHIP

- Culvert Replacement – Roehm Road
- Drainage and Backslopes – Braun Road
- Local Road Dust Control
- Primary Road Dust Control

## SCIO TOWNSHIP

- Fallen Trees – Byington Boulevard, Riverbend Drive
- Limestone Patch – Bandera Drive, Daleview Drive, W Liberty Road, Luella Street, Myrtle Avenue, Park Road, Schevchenko Drive, Stein Road, Tubbs Road, W Delhi Road: 101 tons
- Local Road Dust Control

## SHARON TOWNSHIP

- Drainage and Backslopes – Easudes Road, Sharon Valley Road
- Fallen Trees – Sharon Hollow Road, Sylvan Road
- HMA Resurfacing – Sharon Hollow Road
- Limestone Patch – Bethel Church Road, Sylvan Road: 28 tons
- Below Road Gravel Resurfacing Project – 4,318 tons
- Struthers Road Gravel Resurfacing Project – 7,354 tons
- Sylvan Road Limestone Resurfacing Project – 1,518 tons

## SUPERIOR TOWNSHIP

- Crack Sealing – Ridge Road
- Berming – E Joy Road, Short Street
- Fallen Trees – Plymouth Road
- HMA Resurfacing – Harvest Lane, Panama Court
- Limestone Patch – Cherry Hill Road, Frains Lake Road, Gale Road, Hickman Road, Stommel Road, Vreeland Road: 117 tons
- Local Road Dust Control

## SYLVAN TOWNSHIP

- Boom Mow – Brown Drive, Cavanaugh Lake Road, Glazier Road, Pierce Road, Ridge Road, Sager Road
- Gravel Patch – Liebeck Road: 12 tons
- Local Road Dust Control

## WEBSTER TOWNSHIP

- Boom Mow – Mast Road, Merkel Road, N Territorial Road
- Cut Trees – Merkel Road
- Drainage and Backslopes – Merkel Road
- Ditching – Merkel Road
- Limestone Patch – Base Lake Drive, Huron River Court, Huron River Drive, Strawberry Lake Road, Walsh Road: 107 tons
- Local Road Dust Control
- Barker Road Limestone Resurfacing Project – 7,355 tons

## YORK TOWNSHIP

- Culvert Replacement – Mooreville Road, Willow Road
- HMA Resurfacing – Sanford Road Approach
- Limestone Patch – Arkona Road, Day Road, Willow Road: 42 tons
- Local Road Dust Control
- Repair Sinkhole – Platt Road
- Repair Washout – Dexter Street

## YPSILANTI TOWNSHIP

- Boom Mow – Textile Road
- Crack Sealing – Stony Creek Road
- HMA Resurfacing – Edison Avenue
- Limestone Patch – Bemis Road: 35 tons
- Local Road Dust Control
- Street Sweeping – Textile Road, Tuttle Hill Road

## **NESC REPORT**

Warranty work is on-going.

## **SHOP REPORT**

### Shop Repairs

- New Tire Installation – 11 tires
- Tires Repaired – 6 tires
- Vehicles Serviced – 10
- Vehicles Serviced by Suburban Chevrolet – 6
- Work Orders Completed – 38

## Equipment Repair

Note: Performed several hydraulic and electrical repairs. Rebuilt spray bars for 3 tankers.

- Truck 314 – Replaced 2 NOx sensors and freed up the turbo wastegate linkage
- Truck 240 – Replaced the transmission ECM
- Truck 344 – Replaced a blown radiator hose
- Truck 351 – Reinforced the cab floor and built a new battery box
- Truck 359 – Reattached rusted fenders
- Trailer 89 – Prepped trailer for Buildings and Grounds

## **BUILDING & GROUNDS REPORT**

### Yard One

- Plumbing repairs
- Repaired handicap door opener in office
- Installed A/C unit in server room
- Installed A/C unit in drivers break room
- Installed monitor in shop and drivers break room
- Prepped lockers for paint
- Set-up patio furniture
- Installed CAT cable for Wi-Fi
- Lawn care
- Repaired lights

### Yard Two

- Replaced damaged south gate
- Lawn care

### Yard Three

- Plumbing repairs
- Lawn care

### Yard Four

- Fuel system repairs
- Replaced sight tubes on brine tanks
- Lawn care

### Yard Six

- Installed monitor
- Lawn care
- Repaired garage door
- Installed drop piping in oil separators

### Brine Well

- Lawn care
- Repaired well head
- Changed belt