

**Washtenaw County Road Commission
TOWNSHIP/STAFF REPORT**

For the period of October 12, 2020 thru October 25, 2020

Board Meeting Date: November 3, 2020

TOWNSHIP REPORT

MAINTENANCE

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

ANN ARBOR TOWNSHIP

- Boom Mow – Stein Road
- Cut Trees – Stein Road
- Limestone Patch – Earhart Road: 17 tons
- Limestone Patch Shoulders – Hogback Road: 16 tons
- Limestone Resurfacing Project – Chalmers Drive, Gleaner Hall Road, Stein Road, Warren Road: 3,685 tons

AUGUSTA TOWNSHIP

- Culvert Replacement – Liss Road
- Cut Bleeders – Bunton Road, Hitchingham Road, Judd Road, Liss Road, Macey Road, McKean Road, Talladay Road, Torrey Road, Tuttle Hill Road
- Limestone Patch – Hitchingham Road, Judd Road, Pitman Road, Talladay Road, Tuttle Hill Road: 120 tons
- Roadside Debris – Bunton Road, McCrone Road

BRIDGEWATER TOWNSHIP

- Boom Mow – Parker Road
- Roadside Debris – Austin Road, Boettner Road

DEXTER TOWNSHIP

- Limestone Patch – McKinley Road: 5 tons
- Street Sweeping – Dexter Townhall Road, Hankerd Road, Island Lake Road

FREEDOM TOWNSHIP

- Boom Mow – Bethel Church Road, Parker Road, Rentz Road, Waters Road
- Limestone Patch Shoulders – Pleasant Lake Road: 4 tons
- Repair Washout – Parker Road: 46 tons

LIMA TOWNSHIP

- Boom Mow – Dancer Road, Jerusalem Road, Liberty Road, Loeffler Road, Peckins Road, Scio Church Road, Steinbach Road
- Limestone Patch – Waltrous Road: 7 tons
- Street Sweeping – Jackson Road, Old US-12

LODI TOWNSHIP

- Boom Mow – Parker Road, Strieter Road, Waters Road
- Cut Bleeders – Alber Road, Ellsworth Road, Noble Road, Tessmer Road, Textile Road, Waters Road, Weber Road
- Limestone Patch – Textile Road, Weber Road: 60 tons

LYNDON TOWNSHIP

- Gravel Patch – Boyce Road, Dexter-Pinckney Road: 13 tons
- Limestone Patch – Bartell Road, Goodband Road: 12 tons
- Street Sweeping – Hadley Road

MANCHESTER TOWNSHIP

- Drainage and Backslopes – Boetger Road, English Road, Mulvaney Road, Noggles Road, North Drive, Schleweis Road, Tracey Road
- Fallen Trees – Herman Road

NORTHFIELD TOWNSHIP

- Boom Mow – Jennings Road, Kearney Road, Seven Mile Road, Whitmore Lake Road
- Cleaned Catch Basins – Cherry Court
- Cleaned Crossroad Culvert – E Shore Drive, Nollar Road
- Drainage and Backslopes – Joy Road
- Limestone Patch – Barker Road, Earhart Road, Eight Mile Road, Five Mile Road, Hellner Road, Joy Road, Kearney Road, Maple Road, Northfield Church Road, Seven Mile Road, Spencer Road: 279 tons

PITTSFIELD TOWNSHIP

- Berming – Maple Drive
- Boom Mow – Ellsworth Road, Mission Hills Drive
- Cleaned Drains – Campus Parkway, Carpenter Road, Ellsworth Road, Lohr Road
- HMA Mill – Creekview Court, Creekview Drive, East Horizons Court, East Horizons Drive, Parkview Court, Ping Drive,
- HMA Mill and Fill – Real Quiet Court, Secretariat Drive, Thistle Drive
- Roadside Debris – Textile Road

SALEM TOWNSHIP

- Boom Mow – Brookville Road, Pontiac Trail, Seven Mile Road
- Cut Trees – Chubb Road
- Fallen Trees – Chubb Road
- Limestone Patch – Dixboro Road, Five Mile Road, Gotfredson Road, Napier Road: 159 tons

SALINE TOWNSHIP

- Berming – Arkona Road, Johnson Road, Macon Road, Marion Road
- Cleaned Pipes – Braun Road
- Cut Bleeders – Abel Road, Arkona Road, Hack Road
- Drainage and Backslopes – Braun Road, Macon Road
- Limestone Patch – Macon Road, Mooreville Road: 90 tons
- Primary Road Dust Control – Willow Road: 5,900 gallons
- Repaired Washout – Arkona Road

SCIO TOWNSHIP

- Boom Mow – Staebler Road
- Cleaned Pipes – E Delhi Road, Laurel Hill Road, Parkridge Drive, Railroad Street
- Drainage and Backslopes – E Delhi Road, Huron River Drive, Laurel Hill Road, Parkridge Drive, Railroad Street, Walnut Road
- Limestone Patch Shoulders – Little Lake Court: 15 tons
- Repair Washout – E Delhi Road, Railroad Street

SHARON TOWNSHIP

- Cut Trees – Jacob Road
- Roadside Debris – Sharon Valley Road

SUPERIOR TOWNSHIP

- Drainage and Backslopes – Clark Road
- Fallen Trees – Norfolk Avenue, Prospect Road
- Limestone Patch – Berry Road, Cherry Hill Road, Gotfredson Road, Vreeland Road: 70 tons
- Limestone Patch Shoulders – Leforge Road, Prospect Road, Vreeland Road: 47 tons
- Traffic Control – Superior Road

SYLVAN TOWNSHIP

- Boom Mow – Old US-12, Scio Church Road
- Street Sweeping – Cavanaugh Lake Road, Glazier Road, Kalmbach Road, Old US-12, Ridge Road, Sylvan Road

WEBSTER TOWNSHIP

- Cut Bleeders – Gregory Road, Scully Road, Zeeb Road
- Drainage and Backslopes – Northfield Church Road, Valentine Road
- Gravel Patch – Base Lake Drive: 30 tons
- Limestone Patch – Scully Road: 15 tons

YORK TOWNSHIP

- Cleared Drains – Milkey Road
- Cut Bleeders – Begole Road, Jewell Road, Warner Road
- Drainage and Backslopes – Stony Creek Road
- Fallen Tree – Bolla Road
- HMA Resurfacing – Willis Road Approach at Windy Ridge
- Limestone Patch – Willow Road: 15 tons
- Shoulder Maintenance – Landsend Lane

YPSILANTI TOWNSHIP

- Cleared Drains – Ford Boulevard, Forest Avenue, Grove Road, Harris Road, Holmes Road
- Crack Filling – Bomber Avenue, Bradley Avenue, Cottage Lane, Creekway Court, Creekway Drive, Garden Court, Grove Road, Hearthsides Drive, Ide Avenue, Lakeway Street, McGregor Road, Moeller Avenue, Morris Street, Natalie Court, Natalie Drive, Valley Drive, Woodale Avenue
- Fallen Trees – Merritt Road
- HMA Resurfacing – Congress Street
- Repaired Sinkhole – Congress Street, Valley Drive
- Structure Maintenance – Mission Hills Drive, Russell Street

STATE TRUNKLINE REPORT

- Guardrail Repair – US-23
- Pothole Patching – I-94, US-12, US-23
- Roadside Debris – I-94, US-23

AFTER HOURS CALL-INS

- Debris in Roadway – 20
- Fallen Trees – 10

SHOP REPORT

Shop Repairs

- Work Orders Completed – 67
- New Tire Installation – 4 tires
- Tires Repaired – 7 tires
- Vehicles Serviced – 7

Equipment Repair

- Note: Received, inspected, and calibrated 3 new heavy trucks
- Truck 306 – Replaced air dryer
- Truck 344 – Replaced MCM, EGR actuator and fabricated a DEF pump cover
- Truck 314 – Replaced the NOX sensors
- Truck 330 – Rebuilt fan clutch
- Mower 891 – Replaced the swing cylinder and rebuilt the front stabilizer cylinder

BUILDING & GROUNDS REPORT

Yard One

- Installed new blinds and window film in engineering office
- Installed multiple door seals in shop
- Hung brackets in parking garage for tire chains
- Commercially cleaned building windows
- Repaired water hoses in parking garage
- Setup assembly room for meeting
- Closed patio area for the season
- Repaired oil room door sweep
- Repaired parking lot lighting
- Performed fall clean-up
- Monthly checks

Yard Two

- Commercially cleaned building windows
- Cleaned Mezzanine in shop
- Repaired furnaces in shop
- Replaced belt on rapid unit
- Monthly checks
- Lawnmowing

Yard Three

- Re-secured garage door window
- Replaced shingles on salt barn
- Installed bollard covers
- Monthly checks
- Lawnmowing

Yard Four

- Installed overhead light and vise on work bench in Cold Storage Barn
- Replaced single pane window and re-glazed
- Re-secured soffits and fascia on salt barn
- Monthly checks
- Lawnmowing

Yard Six

- Commercially cleaned building windows
- Repaired gale pit entrance gate
- Replaced pressure washer hose
- Repaired hole on wash bay door
- Monthly checks
- Lawnmowing

Kasier Well

- Replaced and rehung Kaiser Well Sign
- Closed well for the season
- Installed heat tape
- Lawnmowing