

**Washtenaw County Road Commission
TOWNSHIP/STAFF REPORT**

For the period of October 26, 2020 thru November 8, 2020

Board Meeting Date: November 17, 2020

TOWNSHIP REPORT

MAINTENANCE

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

AUGUSTA TOWNSHIP

- Culvert Replacement – Arkona Road, Pitman Road
- Cut Trees – Judd Road, Liss Road
- Limestone Patch – Bunton Road, Butler Road, Hitchingham Road, Judd Road, Liss Road, Macey Road, Rosbolt Road, Sikorski Road, Torrey Road, Tuttle Hill Road, Willow Road: 190 tons
- Limestone Patch Shoulders – Stony Creek Road: 8 tons
- Limestone Resurfacing Project – Liss Road: 819 tons

BRIDGEWATER TOWNSHIP

- Fallen Trees – Sheridan Road
- Gravel Patch – Hogan Road, Neblo Road, Wallace Road: 63 tons
- Limestone Patch – Allen Road, Fisk Road, Hogan Road: 46 tons
- Limestone Patch Shoulders – Austin Road, Clinton Road: 13 tons

DEXTER TOWNSHIP

- Culvert Replacement – Island Lake Road
- Gravel Patch – Rainbow Drive: 6 tons
- Limestone Patch – McKinley Road, Waterloo Road: 8 tons

FREEDOM TOWNSHIP

- Boom Mow – Bethel Church Road, Haab Road, Koebbe Road, Pfaus Road,
- Sheridan Road, Waters Road

LIMA TOWNSHIP

- Boom Mow – Freer Road, Jerusalem Road, Lima Center Road
- Drainage and Backslopes – Fletcher Road, McKinley Road, Scio Church Road, Steinbach Road
- Fallen Trees – Scio Church Road
- Limestone Resurfacing Project – Trinkle Road: 670 tons

LODI TOWNSHIP

- Boom Mow – Ellsworth Road
- HMA Mill and Resurfacing – Pleasant Lake Road

LYNDON TOWNSHIP

- Culvert Replacement – Embury Road, North Lake Road
- Drainage and Backslopes – Embury Road, North Lake Road, North Territorial Road
- Gravel Patch – Cassidy Road, Loveland Road, North Lake Road, Osius Road, Wild Goose Lake Road: 40 tons
- Limestone Patch – Bartell Road, Bowdish Road, Goodband Road, North Lake Road, Osius Road, Roepke Road, Waterloo Road, Wild Goose Lake Road: 33 tons

MANCHESTER TOWNSHIP

- Drainage and Backslopes – Hayes Road, Heim Road, North Drive, Wald Strasse
- Gravel Resurfacing Project – North Drive: 300 tons
- Gravel Patch – Burtless Road: 52 tons

NORTHFIELD TOWNSHIP

- Boom Mow – Kearney Road
- Cleaned Culvert – Jennings Road
- Culvert Replacement – Barker Road, Five Mile Road
- Drainage and Backslopes – Five Mile Road
- Limestone Patch – Earhart Road, Five Mile Road, Hellner Road, Joy Road, Nollar Road, Northfield Church Road, Rushton Road, Six Mile Road: 78 tons

PITTSFIELD TOWNSHIP

- HMA Mill and Resurfacing – Oak Valley Drive
- HMA Resurfacing – Creekview Court, Creekview Drive, East Horizons Court, East Horizons Drive, Parkview Court, Ping Drive

SALEM TOWNSHIP

- Fallen Trees – Dixboro Road, Seven Mile Road, Vorhies Road
- Limestone Patch – Dixboro Road: 17 tons

SALINE TOWNSHIP

- Limestone Patch – Hartman Road, Mooreville Road: 30 tons

SCIO TOWNSHIP

- Boom Mow – Strieter Road
- Cleaned Pipes – Pineview Drive West
- Cut Trees – Stein Road

SHARON TOWNSHIP

- Cut Trees – Jacob Road

SUPERIOR TOWNSHIP

- Hydroseeding – Gale Road Pit
- Limestone Patch Shoulders – Geddes Road, Leforge Road, Prospect Road: 57 tons

SYLVAN TOWNSHIP

- Brush Removal – Sylvan Road
- Culvert Replacement – Bush Road, Kilmer Road
- Drainage and Backslopes – Lingane Road
- Fallen Trees – Bush Road, McLure Road
- Gravel Patch – Bush Road, Loveland Road: 23 tons
- Limestone Patch – Bush Road: 5 tons

WEBSTER TOWNSHIP

- Gravel Patch – Cobble Lane, Cobblestone Lane, Farrell Road, Jennings Road, Northfield Church Road, Scully Road: 15 tons
- Limestone Patch – Base Lake Drive, Chamberlin Road, Walsh Road: 30 tons

YORK TOWNSHIP

- Boom Mow – Milkey Road
- Culvert Replacement – Petersburg Road
- Limestone Patch Shoulders – Stony Creek Road: 12 tons
- Roadside Restoration – Willis Road at Windy Ridge Drive

YPSILANTI TOWNSHIP

- Boom Mow – Bunton Road, Martz Road, Whittaker Road
- Cleaned Drains – Appleridge Street, Big Pine Drive, Blossom Avenue, Cary Drive, Crescent Lane, Davis Street, Debby Court, Dubie Road, Duncan Avenue, Ellsworth Road, Glenwood Avenue, Grove Road, Hawthorne Avenue, Huron Road, Indigo Court, Jonquil Lane, Maplewood Avenue, S Mohawk Avenue, New Meadow Drive, Oaklawn Avenue, Packard Road, Parkwood Avenue, Pinewood Street, Princeton Place, Redwood Avenue, Scott Court, Sunset Trail, Tamarack Lane, Woodruff Lane
- Crack Sealing – Burns Street, Edison Street, Elmhurst Street, Greenside Street, Harding Avenue, McKinley Avenue, Merrill Street, Midvale Avenue, Senate Avenue, Valley Drive, Verna Street
- Culvert Replacement – Whittaker Road
- Drainage and Backslopes – Textile Road
- Fallen Trees – Forest Avenue, Stony Creek Road, Stratford Road
- Limestone Patch – Bemis Road, Ellis Road, Merritt Road, Morgan Road, Munger Road: 168 tons
- Limestone Patch Shoulders – Textile Road: 25 tons
- Roadside Debris – Andrea Street, Bemis Road

STATE TRUNKLINE REPORT

- Cablerail Repair – US-23
- Catch Basin Repair – US-12
- Guardrail Repair – I-94/US-23 interchange, US-23
- Pothole Patching – US-12

AFTER HOURS CALL-INS

- Debris in Roadway – 22
- Fallen Trees – 8

SHOP REPORT

Shop Repairs

- Work Orders Completed – 63
- New Tire Installation – 2 tires
- Tires Repaired – 6 tires
- Vehicles Serviced – 4

Equipment Repair

- Mower 1893 – Replaced the blades cross bar
- Truck 117 – Replaced the wiper linkage assembly
- Truck 214 – Installed salter wiring harness, repaired spinner and tarp
- Truck 320 – Replaced a lift cylinder
- Truck 333 – Replaced rear slack adjusters
- Truck 366 – Winterized and serviced
- Truck 390 – Replaced the air dryer

BUILDING & GROUNDS REPORT

Yard One

- Repaired driver and light in hallway of administration building
- Performed janitorial cleanup in parking garage
- Returned recyclables to local recycling center
- Prepped brine system for winter operations
- Prepped and painted basement walls
- Removed and recycled old chemicals
- Cleaned up dumpster area
- Performed fall cleanup
- Monthly checks
- Lawnmowing

Yard Two

- Removed old material in mezzanine in shop
- Prepped brine system for winter operations
- Returned recyclables to local recycling center
- Monthly checks
- Lawnmowing

Yard Three

- Performed maintenance on furnace and air compressor
- Reworked electrical wiring for garage doors
- Prepped brine system for winter operations
- Replaced and re-glazed garage windows
- Monthly checks
- Lawnmowing

Yard Four

- Performed maintenance on furnace and air compressor
- Prepped brine system for winter operations
- Replaced and re-glazed garage windows
- Adjusted Sharon Pit entrance gate
- Monthly checks
- Lawnmowing

Yard Six

- Installed brine tank in 1-ton pickup for winter operations
- Painted fill line in vertical shaft for fire suppression system
- Prepped brine system for winter operations
- Monthly checks
- Lawnmowing

Kaiser Well

Lawnmowing