

**Washtenaw County Road Commission
TOWNSHIP/STAFF REPORT**

For the period of January 11 thru January 24, 2021

Board Meeting Date: February 2, 2021

TOWNSHIP REPORT

MAINTENANCE

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

ANN ARBOR TOWNSHIP

- Limestone Patch – Earhart Road: 11 tons

AUGUSTA TOWNSHIP

- Limestone Patch – Bunton Road, Hitchingham Road, Judd Road, Liss Road, Rosbolt Road, Talladay Road, Torrey Road, Tuttle Hill road: 55 tons

BRIDGEWATER TOWNSHIP

- Limestone Patch – Hogan Road, Kies Road, Sheridan Road, Willow Road: 86 tons

DEXTER TOWNSHIP

- Boom Mow – Alice Hill Drive, Cavanaugh Lake Road, Cottonwood Lane, Fieldstone Drive, Hidden Lake Circle, Oak Ridge Lane, Rainbow Drive, Stoneyfield Drive
- Gravel Patch – McGuinness Road: 10 tons
- Limestone Patch – Dancer Road, Wylie Road: 12 tons

FREEDOM TOWNSHIP

- Limestone Patch – Bethel Church Road, Hieber Road, Saline Waterworks Road, Steinbach Road: 46 tons

LIMA TOWNSHIP

- Gravel Patch – Wylie Road: 12 tons
- Limestone Patch – McKinley Road: 12 tons

LODI TOWNSHIP

- Boom Mow – Bethel Church Road, Weber Road
- Culvert Replacement – Parker Road
- Cut Trees – Parker Road
- Limestone Patch – Tessmer Road, Waters Road, Zeeb Road: 45 tons

LYNDON TOWNSHIP

- Boom Mow – Goodband Road, Hadley Road

MANCHESTER TOWNSHIP

- Boom Mow – English Road, Grossman Road, Sandborn Road, Schleweis Road
- Gravel Patch – Hudson Road, Noggles Road: 12 tons
- Limestone Patch – Hudson Road, Kirk Road, Noggles Road: 12 tons

NORTHFIELD TOWNSHIP

- Boom Mow – Joy Road, Northfield Church Road
- Fallen Trees – Northfield Church Road
- Limestone Patch – Jennings Road, Joy Road, Kearney Road, Northfield Church Road: 51 tons

PITTSFIELD TOWNSHIP

- Berming – Bemis Road, Merritt Road
- Boom Mow – Ellsworth Road
- Cleaned Drains – Carpenter Road
- Limestone Patch – Bemis Road, Merritt Road, Morgan Road: 180 tons
- Limestone Patch Shoulders – Carpenter Road: 1 ton
- Roadside Debris – Carpenter Road, Maple Road
- Swept Approaches – Bemis Road, Campbell Road, Diamond Street, Iris Lane, Marton Road, Merritt Road, Payeur Road, Stone School Road, Thomas Road, Warner Road

SALINE TOWNSHIP

- Boom Mow – Mooreville Road
- Cut Trees – Mooreville Road
- Limestone Patch – Abel Road, Arkona Road, Braun Road, Case Road, Dell Road, Feldkamp Road, Klager Road, Macon Road, Roehm Road, Sanford Road: 155 tons

SHARON TOWNSHIP

- Boom Mow – Sharon Valley Road
- Cut Trees – Grass Lake Road
- Limestone Patch – Bethel Church Road, Hashley Road, Meyers Road, Waldo Road: 47 tons

SUPERIOR TOWNSHIP

- Limestone Patch – Cherry Hill Road: 27 tons

SYLVAN TOWNSHIP

- Boom Mow – Sylvan Road
- Limestone Patch Shoulders – Notten Road: 9 tons

WEBSTER TOWNSHIP

- Limestone Patch – Pellet Drive, Gregory Road, Northfield Church Road: 40 tons

YORK TOWNSHIP

- Boom Mow – Mooreville Road
- Limestone Patch – Judd Road, Mooreville Road, Warner Road: 40 tons

YPSILANTI TOWNSHIP

- Berming – Bemis Road
- Limestone Patch – Bemis Road, Munger Road: 90 tons
- Limestone Patch Shoulders – Clark Road, Huron Road, Stony Creek Road, Whittaker Road: 11 tons

STATE TRUNKLINE REPORT

- Surface Maintenance – US-12, US-23

AFTER HOURS CALL-INS

- Debris in Roadway – 19
- Fallen Trees – 3
- Icy Roads – 3

WINTER MAINTENANCE

- Crews Responded – 9 times
- Total Salt Used – 2,569
- Total Abrasives Used – 253 tons
- Total Brine Used – 5,889 gallons

SHOP REPORT

Shop Repairs

- Work Orders Completed – 53
- Tires Repaired – 8 tires
- Vehicles Serviced – 8

Equipment Repair

- Mower 1891 – Replaced blade anvil bolts
- Salter 756 – Replaced the auger shaft
- Truck 104 – Replaced ball joints & aligned front end
- Truck 121 – Replaced the radiator and trans cooler lines
- Truck 344 – Replaced 6 injectors, updated fuel system
- Truck 383 – Replaced the power steering pump and radiator
- Truck 387 – Replaced the starter solenoid, tarp and tarp arms
- Truck 390 – Replaced the starter
- Wing Plow 1587 – Welded cracks in the moldboard

BUILDING & GROUNDS REPORT

Yard One

- Monthly building checks
- Snow removal

Yard Two

- Monthly Building Checks

Yard Three

- Repaired exterior garage lighting
- Monthly building checks
- Ran new CAT6 cable
- Built bench for kiosk
- Rehung cabinets
- Painted walls

Yard Four

- Completed office remodel/extension
- Built new bench for kiosk
- Monthly building checks

Yard Six

- Monthly Building Checks