

**Washtenaw County Road Commission
TOWNSHIP/STAFF REPORT**

For the period of February 22 thru March 7, 2021

Board Meeting Date: March 16, 2021

TOWNSHIP REPORT

MAINTENANCE

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

ANN ARBOR TOWNSHIP

- Limestone Patch – Maple Road, Thornoaks Drive: 31 tons

AUGUSTA TOWNSHIP

- Limestone Patch – Bunton Road, Judd Road, Talladay Road, Torrey Road: 85 tons

BRIDGEWATER TOWNSHIP

- Limestone Patch – Braun Road, Fisk Road, Hogan Road, Kaiser Road, Lima Center Road, Neblo Road, Sheridan Road: 59 tons
- Repaired Mailbox – Willow Road

DEXTER TOWNSHIP

- Limestone Patch – Fleming Road, McKinley Road, North Lake Road, Riker Road, Winston Road, Wylie Road: 88 tons

FREEDOM TOWNSHIP

- Drainage – Hieber Road
- Limestone Patch – Eisman Road, Hieber Road: 32 tons

LIMA TOWNSHIP

- Cut Bleeders – Dancer Road, Fletcher Road, Jerusalem Road, Lima Center Road, Sager Road, Steinbach Road, Trinkle Road, Waltrous Road
- Limestone Patch – Beach Road, Easton Road, Dancer Road, Fletcher Road, Guenther Road, Jerusalem Road, Lima Center Road, McKinley Road, Trinkle Road, Wylie Road: 148 tons

LODI TOWNSHIP

- Limestone Patch – Dell Road, Diuble Road, Ellsworth Road, Gensley Road, Saline Waterworks Road, Tessmer Road, Waters Road, Zeeb Road: 165 tons

LYNDON TOWNSHIP

- Cut Bleeders – Bartell Road, Bowdish Road, Boyce Road, Embury Road, Goodband Road, Joslin Lake Road, Mester Road, North Lake Road, Roepke Road
- Limestone Patch – Beeman Road, Bowdish Road, Boyce Road, Joslin Lake Road, Roepke Road: 76 tons

MANCHESTER TOWNSHIP

- Cut Trees – Lakeside Drive
- Limestone Patch – Boetger Road, Burtless Road, Buss Road, English Road, Grossman Road, Herman Road, Henzie Road, Mahrle Road, Noggles Road, Sandborn Road, Schleweis Road: 177 tons
- Repaired Mailbox – Sharon Hollow Road

NORTHFIELD TOWNSHIP

- Boom Mow – Joy Road, Nollar Road, Six Mile Road
- Limestone Patch – Ash Drive, Eight Mile Road, Five Mile Road, Hellner Road, Jennings Road, Joy Road, Kearney Road, Maple Road, Nollar Road, Northfield Church Road, Six Mile Road, Spencer Road: 272 tons

PITTSFIELD TOWNSHIP

- Boom Mow – Ford Boulevard, Harris Road, Parkwood Avenue, Russell Street
- Cut Bleeders – Campbell Road, Marton Road, Morgan Road, Stone School Road, Thomas Road
- Cut Trees – Bemis Road, Ellsworth Road, State Road
- Roadside Debris – Platt Road
- Street Sweeping – Bemis Road, Campbell Road, Carlton Street, Crane Road, Crystal Drive, Diamond Street, Fresno Lane, Hawks Road, Iris Lane, Marton Road, Merritt Road, Morgan Road, Oakdale Drive, Payeur Road, Seminole Street, Stone School Road, Thomas Road, Warner Road

SALEM TOWNSHIP

- Limestone Patch – Brookville Road, Dixboro Road, Five Mile Road, Gotfredson Road, Joy Road, Napier Road, Salem Road, Tower Road: 120 tons
- Roadside Debris – Currie Road

SALINE TOWNSHIP

- Cut Trees – Mooreville Road
- Limestone Patch – Abel Road, Braun Road, Feldkamp Road, Lindsley Road, Macon Road, Parker Road: 106 tons

SCIO TOWNSHIP

- Boom Mow – Baker Road, Scio Church Road, Shield Road, Liberty Road, Parker Road, Zeeb Road
- Gravel Patch – Scio Church Road

SHARON TOWNSHIP

- Cut Trees – Grass Lake Road
- Gravel Patch – Hashley Road, Heim Road, Peckins Road, Waldo Road
- Limestone Patch – Bethel Church Road, Hashley Road, Heim Road, Peckins Road, Sharon Hollow Road, Sharon Valley Road, Smythe Road, Waldo Road, Washburne Road: 155 tons

SUPERIOR TOWNSHIP

- Drainage and Backslopes – Vreeland Road
- Limestone Patch – Berry Road, Cherry Hill Road, Frains Lake Road, Leforge Road, Gotfredson Road, Vreeland Road: 150 tons

SYLVAN TOWNSHIP

- Limestone Patch – Heim Road: 5 tons

WEBSTER TOWNSHIP

- Cut Bleeders – Huron River Drive, Mast Road, North Territorial Road, Walsh Road, Webster Church Road
- Limestone Patch – Huron River Drive, Joy Road, Merrill Road, Pellet Drive, Scully Road, Stein Road, Strawberry Lake Road, Walsh Road, Zeeb Road: 112 tons

YORK TOWNSHIP

- Limestone Patch – Abel Road, Begole Road, Macon Road, Mooreville Road, Willow Road: 40 tons

YPSILANTI TOWNSHIP

- Boom Mow – Centennial Avenue, Clark Road, Ford Boulevard, Harris Road, Holmes Road, Pasadena Street, Prospect Street, Ridge Road, Tyler Road, Wiard Boulevard
- Cut Bleeders – Bemis Road, Ellis Road, Merritt Road, Morgan Road, Munger Road
- Limestone Patch – Bemis Road, Merritt Road, Munger Road: 40 tons
- Road Closure – Textile Road
- Roadside Debris – Golfside Road
- Street Sweeping – Bemis Road, Daytona Street, Ellis Road, Hubbard Street, Merritt Road, Morgan Road, Munger Road, Tuttle Hill Road

STATE TRUNKLINE REPORT

- Surface Maintenance – I-94, M-52, US-23
- Cablerail Repair – I-94
- Guardrail Repair – I-94, M-14, US-23

AFTER HOURS CALL-INS

- Debris in Roadway – 15
- Icy Roads – 1
- Missing Manhole Cover – 1
- Pothole – 1

WINTER MAINTENANCE

- Crews Responded – 5 times
- Total Salt Used – 448 tons
- Total Abrasives Used – 158 tons
- Total Brine Used – 1,409 gallons

SHOP REPORT

Shop Repairs

- Work Orders Completed – 43
- New Tire Installation – 4 tires
- Tires Repaired – 6 tires
- Vehicles Serviced – 10

Equipment Repair

- Car 17 – Replaced all tires
- Grader 461 – Replaced emissions fuel injector head
- RDS Body 714 – Replaced the conveyor drive roller
- Scraper 573 – Replaced center hinge, swing valve, cylinder pin and wear pads
- Truck 215 – Replaced battery
- Truck 315 – Replaced the air compressor
- Truck 351 – De-commissioned, broken subframe
- Truck 373 – Replaced rear driveshaft, rusted through
- Truck 379 – Cleaned all emissions components (DPF, DOC, EGR cooler)
- Truck 384 & 395 – Replaced heated DEF lines
- Truck 388 – Replaced water pump, coolant pipes and tail gate cylinder and control solenoid

BUILDING & GROUNDS REPORT

Yard One

- Pumped out fuel island for upcoming Class B Inspection
- Installed safety sign for parking garage safety shower
- Repaired roof in shipping & receiving area
- Repaired restroom sink in shop
- Repaired restroom sink in parking garage
- Assisted in cleaning oil/water separator
- Cleaned out water in elevator pit
- Repaired south gate operator
- Repaired basement urinal
- Monthly building checks
- Garage maintenance
- Snow removal

Yard Two

- Monthly building checks
- Installed new ceiling tile, LED Lighting, and HVAC diffuser in employee hallway
- Pumped out fuel island for upcoming Class B Inspection
- Repaired furnace in shop
- Removed old breakroom furniture
- Buff and waxed breakroom
- Monthly building checks
- Repaired roof line

Yard Three

- Monthly Building Checks
- Cleaned out oil/water separator and catch basin
- Repaired furnace in parking garage

Yard Four

- Pumped out fuel island for upcoming Class B Inspection
- Cleaned out oil/water separator and catch basin
- Repaired plumbing on Brine System
- Insulated hot water pipes
- Monthly building checks

Yard Six

- Monthly building checks
- Pumped out fuel island for upcoming Class B Inspection