

Washtenaw County Road Commission

Operations Report: 04/12/2021 thru 04/25/2021

Board Meeting Date: May 4, 2021

MAINTENANCE

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

ANN ARBOR TOWNSHIP

- Culvert Replacement – Geddes Road
- Cut Trees – Geddes Road
- Drainage and Backslopes – Geddes Road
- Fallen Trees – Earhart Road
- HMA Crush and Shape – Geddes Road

AUGUSTA TOWNSHIP

- Limestone Patch – Bunton Road, Hitchingham Road, Judd Road, Rosbolt Road, Talladay Road, Tuttle Hill Road: 154 tons

BRIDGEWATER TOWNSHIP

- Boom Mow – Austin Road
- Gravel Patch – Sheridan Road: 15 tons
- Limestone Patch – Kies Road: 11 tons

DEXTER TOWNSHIP

- Limestone Patch – McKinley Road, Stinchfield Woods Road: 14 tons

FREEDOM TOWNSHIP

- Culvert Replacement – Hieber Road
- Gravel Patch – Kothe Road: 12 tons

LIMA TOWNSHIP

- Gravel Patch – Lima Center road, Steinbach Road: 15 tons
- Limestone Patch – Lima Center Road, Steinbach Road: 19 tons

LODI TOWNSHIP

- Boom Mow – Ellsworth Road, Gensley Road, Lone Oak Drive, Strieter Road
- Cleaned Culverts – Parker Road
- Grind Stumps – Parker Road
- Limestone Patch – Alber Road, Huron River Drive, Textile Road, Weber Road, Zeeb Road: 45 tons
- Repair Washout – Wagner Road

LYNDON TOWNSHIP

- Limestone Patch – Bush Road, Roepke Road: 20 tons

MANCHESTER TOWNSHIP

- Gravel Patch – Burtless Road, Henzie Road, Hudson Road, Lemm Road, Mahrle Road, Mull Road, Van Tuyle Road: 63 tons
- Limestone Patch – Hudson Road, Lemm Road, Mahrle Road, Van Tuyle Road: 15 tons
- Roadside Debris – Mulvaney Road

NORTHFIELD TOWNSHIP

- Limestone Patch – Earhart Road, Eight Mile Road, Earhart Road, Jennings road, Lincoln Drive, Maple Road, Six Mile Road: 150 tons

PITTSFIELD TOWNSHIP

- Roadside Debris – Carpenter Road

SALEM TOWNSHIP

- Boom Mow – Dixboro Road
- Limestone Patch – Joy Road: 15 tons

SALINE TOWNSHIP

- Berming – Mooreville Road
- Cleaned Culverts – Parker Road
- Drainage and Backslopes – Macon Road, Mooreville Road
- Limestone Patch – Hartman Road, Mooreville Road, Schill Road: 45 tons

SCIO TOWNSHIP

- Berming – Miller Road
- Boom Mow – E. Delhi, W. Delhi, Tubbs Road
- Culvert Replacement – Miller Road, Park Road
- Drainage and Backslopes – Miller Road
- Limestone Patch – Pratt Road, Staebler Road: 20 tons
- Repair Washout – Zeeb Road

SHARON TOWNSHIP

- Drainage and Backslopes – Grass Lake Road
- Gravel Patch – Hazel Road, Smythe Road, Sharon Hollow Road, Sylvan Road, Washburne Road: 30 tons
- Grind Stumps – Grass Lake Road

SUPERIOR TOWNSHIP

- Cleaned Culvert – Warren Road
- Culvert Replacement – Cherry Hill Road
- Cut Trees – Geddes Road
- Drainage Improvements – Geddes Road
- Forestry – Geddes Road
- HMA Crush and Shape – Geddes Road
- Limestone Patch – Geddes Road, Hickman Road: 65 tons

SYLVAN TOWNSHIP

- Gravel Patch – Loveland Road: 8 tons

WEBSTER TOWNSHIP

- Limestone Patch – Barker Road, Huron River Drive, Northfield Church Road, Scully Road: 55 tons
- Repair Washout – Mast Road, North Territorial Road

YORK TOWNSHIP

- Berming – Mooreville Road
- Limestone Patch – Arkona Road: 15 tons
- Roadside Debris – Crane Road

YPSILANTI TOWNSHIP

- Boom Mow – Amrhein Drive, Bunton Road, Grove Road, Munger Road, Rawsonville Road
- Cut Trees – Munger Road
- Fallen Trees – Devonshire Street, Greenside Street, Hawthorne Avenue, Huron River Drive, Kansas Avenue, Oregon Street, Tyler Road
- Structure Maintenance – Gattegno Street, Muirfield Drive, Streamwood Drive

STATE TRUNKLINE REPORT

- Guardrail Repair – US-23
- Roadside Debris – I-94, US-23
- Surface Maintenance – US-23
- Shoulder Maintenance – I-94 ramps

AFTER HOURS CALL-INS

- Debris in Roadway – 16
- Fallen Trees – 2
- Pothole – 2

WINTER MAINTENANCE

- Crews Responded – 1 time
- Total Salt Used – 82 tons

SHOP REPORT

Shop Repairs

- Work Orders Completed – 55
- New Tire Installation – 10 tires
- Tires Repaired – 13 tires
- Vehicles Serviced – 10

Equipment Repair

- Grader 452 – Decommissioned grader for programmed trade-in
- Grader 471 – Adjusted valves and had the DOC and DPF cleaned
- Roller 1082 – Prepped new vibratory roller
- Truck 191 – Rebuilt the front end and had it aligned
- Truck 234 – Repaired paint damage
- Truck 336 – Replaced the defrost actuator and a steering u-joint
- Truck 387 – Replaced the NOx sensor harness
- Truck 390 – Replaced the radiator and midship bearing

BUILDING & GROUNDS REPORT

Yard One

- Unclogged kitchenette sink in Finance Department
- Replaced air regulator in Shop
- Assisted mechanics in painting truck body
- Installed water meter on hydrant
- Replaced drinking fountain filter
- Repaired lobby door enclosure
- Installed fire alarm system
- Installed hand sanitizer
- Unclogged garage sink
- Garage maintenance
- Winter maintenance
- Lawnmowing

Yard Two

- Regraded greenspace and buried downspouts
- Installed fire alarm system
- Lawnmowing

Yard Three

- Lawnmowing

Yard Four

- Locker Install
- Lawnmowing

Yard Six

- Lawnmowing
- Installed warning light in pump house
- Repaired entrance gate