

Washtenaw County Road Commission

Operations Report: 01/10/2022 thru 01/23/2022

Board Meeting Date: February 1, 2022

MAINTENANCE

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

ANN ARBOR TOWNSHIP

- Limestone Patch – Blakeway Street, Maple Road, Stein Road, Woodland Road: 60 tons
- Limestone Patch Shoulders – Dixboro Road: 5 tons

AUGUSTA TOWNSHIP

- Boom Mow – Macey Road, McKean Road, Judd Road, Talladay Road, Tuttle Hill Road
- Fallen Trees – McCrone Road
- Limestone Patch – Arkona Road, Bemis Road, Bunton Road, Judd Road, Liss Road, Torrey Road, Tuttle Hill Road, Willis Road, Willow Road: 137 tons

BRIDGEWATER TOWNSHIP

- Boom Mow – Austin Road
- Grind Stumps – Clinton Road
- Limestone Patch – Arkona Road, Braun Road, Fisk Road, Hack Road, Lima Center Road, McCollum Road, Neal Road, Schellenberger Road, Willow Road: 65 tons
- Roadside Debris – Burmeister Road, Fisk Road, Lima Center Road

DEXTER TOWNSHIP

- Cut Trees – Hankerd Road

FREEDOM TOWNSHIP

- Boom Mow – Bethel Church Road, Kothe Road, Schneider Road
- Limestone Patch – Bethel Church Road, Haab Road, Schellenberger Road, Spies Road: 37 tons

LIMA TOWNSHIP

- Cut Trees – Dancer Road, Fletcher Road
- Roadside Debris – Klinger Road

LODI TOWNSHIP

- Culvert Replacement – Saline Waterworks Road
- Drainage and Backslopes – Zeeb Road
- Limestone Patch – Bethel Church Road, Weber Road: 30 tons

LYNDON TOWNSHIP

- Limestone Patch – Cassidy Road, Goodband Road: 13 tons

MANCHESTER TOWNSHIP

- Gravel Patch – Lemm Road: 10 tons
- Grind Stumps – Logan Road, Wellwood Road
- Limestone Patch – Bowens Road, Herman Road, Lemm Road, Logan Road, Wellwood Road: 77 tons

NORTHFIELD TOWNSHIP

- Cut Trees – Rushton Road, Spencer Road, Sutton Road
- Limestone Patch – Earhart Road, Five Mile Road, Joy Road, Kearney Road, Nollar Road, Northfield Church Road, Phlox Drive, Six Mile Road, Spencer Road: 304 tons

PITTSFIELD TOWNSHIP

- Boom Mow – Morgan Road, Stone School Road
- Roadside Debris – State Road

SALEM TOWNSHIP

- Limestone Patch – Brookville Road, Chubb Road, Dixboro Road, Five Mile Road, Salem Road, Tower Road: 215 tons
- Roadside Debris – Pontiac Trail

SCIO TOWNSHIP

- Drainage and Backslopes – Huron River Drive
- Limestone Patch – Burton Avenue, Liberty Road, Luella Avenue, Park Road, Staebler Road: 15 tons

SHARON TOWNSHIP

- Fallen Trees – Parr Road
- Gravel Patch – Easudes Road, Heim Road, Jacob Road, Sharon Hollow Road, Struthers Road, Sylvan Road, Waldo Road, Walker Road, Wingate Road: 55 tons
- Limestone Patch – Bethel Church Road, Sharon Hollow Road, Walker Road: 30 tons

SUPERIOR TOWNSHIP

- Fallen Trees – Sharon Hollow Road
- Limestone Patch – Cherry Hill Road, Frains Lake Road, Gotfredson Road, Vorhies Road, Vreeland Road: 232 tons
- Limestone Patch Shoulders – Plymouth Road: 6 tons
- Roadside Debris – Prospect Road

SYLVAN TOWNSHIP

- Roadside Debris – Old US-12

WEBSTER TOWNSHIP

- Limestone Patch – Base Lake Drive: 15 tons

YORK TOWNSHIP

- Boom Mow – Bunton Road, Moon Road, Milkey Road

YPSILANTI TOWNSHIP

- Boom Mow – Bemis Road, Huron River Drive, Mott Road, Munger Road
- Cut Trees – Bemis Road, Chevrolet Street
- Ground Stumps – Grove Road, Juneau Road, Martz Road, McKinley Avenue
- Limestone Patch – Bemis Road, Ellis Road, Merritt Road, Munger Road: 110 tons
- Roadside Debris – Grove Road, Merritt Road

STATE TRUNKLINE REPORT

- Cable Rail Repair – US-23
- Surface Maintenance – I-94, US-12

AFTER HOURS CALL-INS

- Debris in Roadway – 11
- Damaged Guardrail – 1

WINTER MAINTENANCE

- Crews Responded – 5 times
- Total Salt Used – 892 tons
- Total Abrasives Used – 219 tons
- Total Brine Used – 1370 gallons

SHOP REPORT

Shop Repairs

- Work Orders Completed – 49
- New Tire Installation – 1
- Tires Repaired – 9
- Vehicles Serviced – 6
- Service Call Runs – 4

Equipment Repair

- Grader 463 – Welded the front fender brackets
- Truck 140 – Replaced the battery
- Truck 219 – Replaced the front brakes
- Truck 387 – Replaced all rear brake chambers & slack adjusters
- Truck 388 – Replaced the carrier bearing, NOx sensors & scraper swing cylinders

BUILDING & GROUNDS REPORT

Yard One

- Removed trash and scrap steel
- Repaired service door closer
- Repaired water hose reel
- Repaired exterior building lights
- Cleaned out drain in office sink
- Repaired garbage disposal in kitchen
- Repaired emergency exit lighting
- Monthly building checks

Yard Two

- Replaced high bay lights in shop and parking garage
- Repaired valve on brine system
- Monthly building checks

Yard Three

- Replaced shingles on salt barn
- Repaired roof on cold storage barn
- Monthly building checks

Yard Four

- Serviced overhead electric heaters
- Repaired air line regulator
- Repaired roof leaks
- Replaced shingles on salt barn
- Monthly building checks

Yard Six

- Replaced cover on heater unit
- Repaired plumbing for power washing units
- Monthly building checks