

Washtenaw County Road Commission

Operations Report: 08/08/2022 thru 08/28/2022

Board Meeting Date: September 6, 2022

MAINTENANCE

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

ANN ARBOR TOWNSHIP

- Boom Mow – Earhart Place
- Drainage and Backslopes – Earhart Place
- Fallen Trees – Hogback Road
- Fog Seal – Arrowhead Drive, Geddes Road, Goss Road, Maple Road, Newport Road, Woodbridge Avenue
- Limestone Patch Shoulders – Danbury Lane, Dhu Varren Road, Englave Drive: 10 tons
- Local Road Dust Control

AUGUSTA TOWNSHIP

- Berming – Rawsonville Road
- Boom Mow – Hitchingham Road, Talladay Road
- Culvert Replacement – Hitchingham Road
- Fallen Trees – Arkona Road, Judd Road
- Fog Seal – Whittaker Road
- Limestone Patch – Bunton Road: 30 tons
- Limestone Patch Shoulders – Stony Creek Road, Willis Road: 2 tons
- Local Road Dust Control

BRIDGEWATER TOWNSHIP

- Drainage and Backslopes – Arkona Road, Hogan Road, McCollum Road, Willow Road
- Fallen Trees – Austin Road
- Gravel Patch – Arkona Road: 20 tons
- Local Road Dust Control
- Primary Road Dust Control

DEXTER TOWNSHIP

- Limestone Patch – Madden Road, Riker Road: 45 tons
- Local Road Dust Control
- Primary Road Dust Control

FREEDOM TOWNSHIP

- Culvert Replacement – Pfaus Road
- Gravel Patch – Bethel Church Road, Kothe Road, Rentz Road: 66 tons
- Limestone Patch – Rentz Road: 7 tons
- Local Road Dust Control
- Primary Road Dust Control

LIMA TOWNSHIP

- Boom Mow – Wylie Road
- Debris in Roadway – Wylie Road
- Local Road Dust Control
- Gravel Road Resurfacing Project: Trinkle Road: 4,092 tons
- Repair Washouts – Fletcher Road, Jerusalem Road, Sager Road, Waltrous Road
- Structure Maintenance – Dancer Road

LODI TOWNSHIP

- Berming – Dell Road, Weber Road
- Gravel Patch – Alber Road, Bethel Church Road, Grass Road, Noble Road, Saline Waterworks Road, Textile Road, Waters Road, Weber Road, Zeeb Road: 12 tons
- Limestone Patch – Alber Road, Bethel Church Road, Grass Road, Noble Road, Saline Waterworks Road, Textile Road, Waters Road, Weber Road, Zeeb Road: 15 tons
- Primary Road Dust Control

LYNDON TOWNSHIP

- Fog Seal – Hadley Road, Island Lake Road, Stofer Road, Werkner Road
- Gravel Patch – Beeman Road, Bowdish Road, Boyce Road, Bush Road, Clark Lake Road, Lingane Road, Loveland Road, Roe Road: 30 tons
- Limestone Patch – Beeman Road, Bowdish Road, Boyce Road, Bush Road, Clark Lake Road, Lingane Road, Loveland Road, Roe Road: 15 tons
- Limestone Resurfacing Project – Roepke Road: 13,080 tons
- Primary Road Dust Control
- Repair Washouts – Bush Road, Guinan Drive: 25 tons

MANCHESTER TOWNSHIP

- Drainage and Backslopes – Herman Road, Tracey Road
- Gravel Patch – Bowens Road, Schleweis Road, VanTuyle Road: 50 tons

NORTHFIELD TOWNSHIP

- Boom Mow – Earhart Road, Joy Road
- Limestone Patch – Earhart Road, Five Mile Road, Ford Road, Hellner Road, Jennings Road, Joy Road, Kearney Road, Maple Road, Northfield Church Road, Nollar Road, Six Mile Road, Spencer Road: 209 tons
- Limestone Resurfacing Project: Six Mile Road, Sutton Road: 6,401 tons
- Local Road Dust Control

PITTSFIELD TOWNSHIP

- Berming – Merritt Road
- Canopy Cutting – Crane Road
- Cleaned Culvert – Crane Road
- Cleaned Drains – Ellsworth Road
- Fog Seal – Ellsworth Road, Maple Road
- Limestone Patch Shoulders – Carpenter Road, Lohr Road, Maple Road: 61 tons
- Limestone Resurfacing Project – Crane Road, Merritt Road, Morgan Road: 4,434 tons
- Concrete Curb and Gutters and ADA Ramps – Maple Road, Ellsworth Road, Green Valley Drive, Gyers Meadows Drive
- HMA Mill and Fill – Warner Creek Subdivision

SALEM TOWNSHIP

- Boom Mow – Curtis Road, Dixboro Road, North Territorial Road, Six Mile Road
- Fallen Trees – Five Mile Road
- Fog Seal – North Territorial Road
- Limestone Patch – Dixboro Road, Weed Road: 147 tons

SCIO TOWNSHIP

- Boom Mow – Park Road, Pratt Road, Staebler Road
- Fog Seal – Miller Road
- Local Road Dust Control

SHARON TOWNSHIP

- Drainage and Backslopes – Washburne Road
- Fallen Trees – Sharon Valley Road
- Gravel Patch – Meyers Road: 40 tons
- Gravel Resurfacing Project: Sharon Valley Road: 100 tons

SUPERIOR TOWNSHIP

- Fallen Trees – Geddes Road, Stamford Road
- Fog Seal – Geddes Road, Plymouth Road
- Street Sweep Aprons – Plymouth Road

SYLVAN TOWNSHIP

- Berming – Cavanaugh Lake Road
- Boom Mow – Bush Road, Cavanaugh Lake Road, Old US-12
- Fog Seal – Cavanaugh Lake Road, Werkner Road
- Gravel Resurfacing Project – Fahrner Road, Garvey Road: 2,254
- Local Road Dust Control

WEBSTER TOWNSHIP

- Boom Mow – Donovan Road, Huron River Drive, Jennings Road, Joy Road, North Territorial Road, Zeeb Road
- Cut Bleeders – Chamberlin Road, Gregory Road, Merkel Road, Vaughn Road, Zeeb Road
- Drainage and Backslopes – Huron River Drive
- Ditching – Huron River Drive
- Fog Seal – Island Lake Road, Webster Church Road
- Local Road Dust Control
- Primary Road Dust Control
- Repair Washouts – Danell Drive, Pine Tree Lane, Sunrise Drive, Yankee Lane

YORK TOWNSHIP

- Boom Mow – Maple Road
- Limestone Patch Shoulders – Carpenter Road: 13 tons
- Local Road Dust Control

YPSILANTI TOWNSHIP

- Brush Removal – Dupont Avenue
- Cleared Drains – Hewitt Road
- Debris in Roadway – Bemis Road, Stony Creek Road
- Drainage and Backslopes – Lakeview Avenue
- Fallen Trees – Scott Court
- Fog Seal – Congress Street
- Limestone Patch Shoulders – Clark Road, Huron Road, McGregor Road, Ridge Road, Stony Creek Road, Textile Road, Whittaker Road, William Avenue : 16 tons

STATE TRUNKLINE REPORT

- Surface Maintenance – I-94
- Guardrail – M-14

AFTER HOURS CALL-INS

- Fallen Tree – 13
- Debris in the Roadway – 29
- Water Over Road – 2
- Road Defect – 1

SHOP REPORT

Shop Repair

- Work Orders Completed – 74
- New Tire Installation – 6 tires
- Tires Repaired – 6 tires
- Vehicles Serviced – 17
- Service Call Runs - 7

Equipment Repair

- Truck 206 – Reinforced spray bar travel supports
- Truck 122 – Replaced front brake calipers
- Truck 127 – Replaced a transmission cooler hose
- Boom Mower 1892 – Rebuilt the blades spindle
- Truck 346 - Rebuilt plumbing from pump
- Truck 304 – Replaced the starter
- Truck 373 – Replaced the radiator, CAC, resealed a hydraulic valve
- Truck 367 – Replaced the 4 rear brake chambers
- Truck 191 & 390 – Replaced water pumps.

BUILDING & GROUNDS REPORT

Yard One

- Repaired card reader at South gate
- Repaired electrical outlets in mechanic's shop
- Repaired electrical connections on brine pump system
- Removed trash, scrap steel and recycling
- Serviced brine pump
- Replaced light bulbs
- Repaired plumbing in garage and shop bathrooms
- Repaired fuel pumps
- Cleaned out shop and garage floor drains and yard oil separator
- Performed monthly building checks
- Mowed

Yard Two

- Repaired property fence
- Replaced brine fill hose
- Serviced brine pump
- Repaired burrowing animal damage
- Repaired North and South slide gates
- Serviced air conditioning unit and cleaned coils
- Repaired plumbing in restrooms
- Cleaned out oil separator
- Performed monthly building checks
- Mowed

Yard Three

- Serviced brine pump
- Performed monthly building checks
- Mowed

Yard Four

- Serviced and adjusted brine pump
- Replaced brine hose
- Performed monthly building checks
- Mowed

Yard Six

- Repaired fuel pump handles
- Replaced control box on well
- Serviced brine pump
- Repaired yard entry slide gate
- Repaired overhead garage door
- Repaired air handler and serviced air conditioning unit
- Cleaned out garage floor drains and oil separators
- Performed monthly building checks
- Mowed

Kaiser Mineral Brine Well

- Repaired burrowing animal damage
- Installed new water lines for fresh water well
- Mowed