

Washtenaw County Road Commission

Operations Report: 08/29/2022 thru 09/11/2022

Board Meeting Date: September 20, 2022

MAINTENANCE

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

ANN ARBOR TOWNSHIP

- Limestone Resurfacing Project – Englave Drive, Stein Road, Warren Road: 1,713 tons
- Local Road Dust Control

AUGUSTA TOWNSHIP

- Boom Mow – Arkona Road, Whittaker Road, Willis Road
- Culvert Replacement – Hitchingham Road
- Limestone Patch – Talladay Road, Tuttle Hill Road: 75 tons

BRIDGEWATER TOWNSHIP

- Cleaned Culvert – Kies Road
- Crack Filling – Bartlett Road
- Fallen Trees – Burmeister Road
- Limestone Patch – Kies Road: 101 tons
- Limestone Patch Shoulders – Austin Road: 16 tons

DEXTER TOWNSHIP

- Fallen Trees – Hankerd Road
- Limestone Patch – Madden Road, Noah Road: 14 tons
- Limestone Resurfacing Project: Riker Road: 6,962 tons
- Shoulder Maintenance – North Territorial Road

FREEDOM TOWNSHIP

- Culvert Replacement – Waters Road
- Cut Trees – Haab Road
- Drainage and Backslopes – Ellsworth Road, Lima Center Road, Spies Road, Steinbach Road, Waters Road
- Fallen Trees – Eisman Road, Ellsworth Road, Haab Road, Lima Center Road, Loeffler Road, Rentz Road, Schmitz Road, Steinbach Road, Waters Road

LIMA TOWNSHIP

- Boom Mow – Jerusalem Road, Loeffler Road, Peckins Road, Sager Road, Waltrous Road
- Gravel Patch – Dancer Road: 9 tons
- Limestone Patch – Dancer Road: 5 tons
- Limestone Patch Shoulders – Luick Drive: 2 tons
- Repair Washout – Sager Road, Waltrous Road

LODI TOWNSHIP

- Culvert Replacement – Weber Road
- Local Road Dust Control

LYNDON TOWNSHIP

- Boom Mow – First Street, Second Street, Wild Goose Lake Road
- Gravel Patch – Boyce Road, Joslin Lake Road, Loveland Road: 13 tons
- Gravel Patch Shoulders – North Territorial Road, Waterloo Road: 1 ton
- Limestone Patch – Loveland Road: 10 tons
- Local Road Dust Control
- Repair Washouts – Bartell Road, Embury Road

MANCHESTER TOWNSHIP

- Boom Mow – Sharon Hollow Road
- Gravel Patch – Tracey Road: 10 tons
- Limestone Patch – Austin Road, Sharon Hollow Road, Tracey Road: 37 tons

NORTHFIELD TOWNSHIP

- Fallen Trees – Joy Road
- Fog Seal – North Territorial Road
- Limestone Resurfacing Project: Rushton Road, Six Mile Road: 3,906 tons

PITTSFIELD TOWNSHIP

- Boom Mow – Ann Arbor-Saline Road
- Cleared Drains – Carpenter Road, Textile Road
- Fallen Trees – Bemis Road, Lohr Road, Rolling Meadows Lane, Textile Road, Warner Road, Wilson Road
- Debris in Roadway – Lohr Circle
- Local Road Dust Control

SALEM TOWNSHIP

- Fallen Trees – Angle Road, Brookville Road, Joy Road, Pontiac Trail, Seven Mile Road
- Limestone Patch – Dixboro Road, Napier Road: 161 tons

SHARON TOWNSHIP

- Culvert Replacement – Jacob Road
- Fallen Trees – Hashley Road, Heim Road, Jacob Road, Peckins Road, Sharon Hollow Road, Smythe Road, Sylvan Road
- Gravel Patch – Bethel Church Road, Hazel Road, Jacob Road, Kendall Road, Prospect Hill Road, Sharon Hollow Road, Sylvan Road: 105 tons
- Limestone Patch – Bethel Church Road, Grass Lake Road, Kendall Road, Prospect Hill Road, Sylvan Road: 43 tons
- Local Road Dust Control

SUPERIOR TOWNSHIP

- Fallen Trees – Barrington Drive, Cherry Hill Road, Harris Road, Superior Road
- Limestone Patch Shoulders – Prospect Road: 14 tons
- Limestone Resurfacing Project – Gotfredson Road: 1,509 tons
- Local Road Dust Control

SYLVAN TOWNSHIP

- Boom Mow – Old US-12, Sylvan Road
- Culvert Replacement – Bush Road
- Cut Trees – Bush Road
- Limestone Patch Shoulders – Kalmbach Road: 3 tons
- Local Road Dust Control

WEBSTER TOWNSHIP

- Drainage and Backslopes – Farrell Road, Hamburg Road, Walsh Road
- Fog Seal – North Territorial Road
- Local Road Dust Control

YORK TOWNSHIP

- Boom Mow – Arkona Road
- Fallen Trees – Hack Road, Moon Road, Platt Road, Willis Road
- Limestone Patch – Arkona Road: 30 tons

YPSILANTI TOWNSHIP

- Cleaned Catch Basin – Nash Avenue
- Cleared Drains – Carpenter Road, Cross Street, Ford Boulevard, Forest Avenue, Grove Road, Harris Road, Merritt Road, Textile Road, Tyler Road
- Cut Trees – Eileen Street
- Debris in Roadway – Bemis Road
- Fallen Trees – Aspen Way, Bemis Road, Buick Avenue, Campbell Avenue, Ellis Road, Harding Avenue, Hillcrest Boulevard, Hitchingham Road, Harris Road, Kewanee Street, Maplewood Avenue, Munger Road, Rosewood Avenue, Stony Creek Road, Stratford Road, Textile Road, Tuttle Hill Road, Whittaker Road, Woodlawn Avenue
- Local Road Dust Control

STATE TRUNKLINE REPORT

- Guardrail – US-23 between Plymouth rd and I-94

AFTER HOURS CALL-INS

- Fallen Tree – 62
- Debris in the Roadway – 16
- Damaged Guardrail – 1

SHOP REPORT

Shop Repair

- Work Orders Completed – 46
- New Tire Installation – 19 tires
- Tires Repaired – 9 tires
- Vehicles Serviced – 7
- Service Call Runs - 4

Equipment Repair

- Boom Mower 892 – Rebuilt the spindle head
- Broom 1080 – Replaced the hydraulic motor & drive hub
- Pickup 176 – Replaced the ball joints and aligned the front end
- Scraper 590 – Replaced all the hydraulic pipes & hoses
- Truck 191 – Replaced the water pump
- Truck 316 – Resealed the hydraulic valves
- Truck 389 – Replaced all rear brakes & resealed all hydraulic valves

BUILDING & GROUNDS REPORT

Yard One

- Repaired electrical at brine pump system
- Replaced lights in parking garage
- Installed new water lines and hose reel
- Repaired overhead garage door in mechanic's shop
- Repaired air lines in parking garage
- Prepared snow push box for winter maintenance
- Repaired service door in shop
- Performed monthly building checks
- Removed trash and scrap steel
- Mowed

Yard Two

- Repaired emergency exit lights
- Repaired bathroom plumbing

Yard Three

- Replaced shingles on salt barn roof
- Repaired yard and flagpole lighting
- Performed monthly building checks
- Mowed

Yard Four

- Repaired air conditioning condenser fan motor and belts
- Repaired overhead garage door and door sensors
- Replaced yard flood lights
- Mowed

Yard Six

- Repaired yard and flagpole lighting
- Performed monthly building checks
- Mowed

Kaiser Mineral Brine Well

- Mowed